


janv-11																														
01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31

 brouillard observé (même léger)  
 brouillard prévue  
 meteo :  
 matin du 01 octobre : leger brouillard




19/01:comptes a 0, calibration faite  
 nuit du 05 au 06 : coupure courant




18/01:wls70 installé a cote de wls7


en route depuis le 07 oct 15h25 Tu




manque 1 sonde  
 donnees a rapatrier par clef usb (JC\_rien sur basesirta)



21/01:remise du continuum



passé en mode cloud le 11/01/2011 (14h20 TU)



 **Données complètes**   
  **Données incomplètes**   
  **Instruments non installés**  
**F** Lampe flash changée    **C** Calibration  
 en cours